

Übersicht Baugrößen CUSTOM-LINE



| Generatorbezeichnung | Ausgangsleistung in kW (100% ED) | Stromaufnahme | | Abmessung B x H x T in mm | Gewicht in kg |
|----------------------|-------------------------------------|---------------|---------------|------------------------------|------------------|
| | | in A bei 400V | in A bei 480V | | |
| MF | | | | | |
| MF 5 | 5 | 9 | 8 | B=1000 H=2100 T=500 | ≈ 350 |
| MF 10 | 10 | 18 | 15 | B=1000 H=2100 T=500 | ≈ 350 |
| MF 15 | 15 | 28 | 23 | B=1000 H=2100 T=500 | ≈ 350 |
| MF 20 | 20 | 37 | 31 | B=1000 H=2100 T=500 | ≈ 350 |
| MF 30 | 30 | 55 | 46 | B=1000 H=2100 T=500 | ≈ 350 |
| MF 5x2 | 5 | 18 | 15 | B=1000 H=2100 T=500 | ≈ 400 |
| MF 10x2 | 10 | 37 | 31 | B=1000 H=2100 T=500 | ≈ 400 |
| MF 15x2 | 15 | 55 | 46 | B=1000 H=2100 T=500 | ≈ 400 |
| MF 20x2 | 20 | 74 | 61 | B=1000 H=2100 T=500 | ≈ 400 |
| MF 30x2 | 30 | 111 | 92 | B=1000 H=2100 T=500 | ≈ 400 |
| MF 5x3 | 5 | 28 | 23 | B=1400 H=2200 T=600 | ≈ 550 |
| MF 10x3 | 10 | 55 | 46 | B=1400 H=2200 T=600 | ≈ 550 |
| MF 15x3 | 15 | 83 | 69 | B=1400 H=2200 T=600 | ≈ 550 |
| MF 20x3 | 20 | 111 | 92 | B=1400 H=2200 T=600 | ≈ 550 |
| MF 30x3 | 30 | 166 | 138 | B=1400 H=2200 T=600 | ≈ 550 |
| MF 5x4 | 5 | 37 | 31 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 10x4 | 10 | 74 | 61 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 15x4 | 15 | 111 | 92 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 20x4 | 20 | 148 | 123 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 30x4 | 30 | 221 | 184 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 5x5 | 5 | 46 | 38 | B=2400 H=2200 T=600 | ≈ 850 |
| MF 10x5 | 10 | 92 | 77 | B=2400 H=2200 T=600 | ≈ 850 |
| MF 15x5 | 15 | 138 | 115 | B=2400 H=2200 T=600 | ≈ 850 |
| MF 20x5 | 20 | 184 | 154 | B=2400 H=2200 T=600 | ≈ 850 |
| MF 30x5 | 30 | 277 | 231 | B=2400 H=2200 T=600 | ≈ 850 |
| MF 5x6 | 5 | 55 | 46 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 10x6 | 10 | 111 | 92 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 15x6 | 15 | 166 | 138 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 20x6 | 20 | 221 | 184 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 30x6 | 30 | 332 | 277 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 5x7 | 5 | 65 | 54 | B=2400 H=2200 T=600 | ≈ 950 |
| MF 10x7 | 10 | 129 | 108 | B=2400 H=2200 T=600 | ≈ 950 |
| MF 15x7 | 15 | 194 | 161 | B=2400 H=2200 T=600 | ≈ 950 |
| MF 20x7 | 20 | 258 | 215 | B=2400 H=2200 T=600 | ≈ 950 |
| MF 30x7 | 30 | 387 | 323 | B=2400 H=2200 T=600 | ≈ 950 |
| MF 5x8 | 5 | 74 | 61 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 10x8 | 10 | 148 | 123 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 15x8 | 15 | 221 | 184 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 20x8 | 20 | 295 | 246 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 30x8 | 30 | 443 | 369 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 20 | 20 | 37 | 31 | B=1200 H=2200 T=600 | ≈ 500 |
| MF 30 | 30 | 55 | 46 | B=1200 H=2200 T=600 | ≈ 500 |
| MF 20-2A | 20 | 37 | 31 | B=1200 H=2200 T=600 | ≈ 500 |
| MF 30-2A | 30 | 55 | 46 | B=1200 H=2200 T=600 | ≈ 500 |
| MF 20x2 | 20 | 74 | 61 | B=1200 H=2200 T=600 | ≈ 500 |
| MF 30x2 | 30 | 111 | 92 | B=1200 H=2200 T=600 | ≈ 500 |
| MF 5x3 | 5 | 28 | 23 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 10x3 | 10 | 55 | 46 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 15x3 | 15 | 83 | 69 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 20x3 | 20 | 111 | 92 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 30x3 | 30 | 166 | 138 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 5x4 | 5 | 37 | 31 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 10x4 | 10 | 74 | 61 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 15x4 | 15 | 111 | 92 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 20x4 | 20 | 148 | 123 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 30x4 | 30 | 221 | 184 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 5x5 | 5 | 46 | 38 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 10x5 | 10 | 92 | 77 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 15x5 | 15 | 138 | 115 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 20x5 | 20 | 184 | 154 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 30x5 | 30 | 277 | 231 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 5x6 | 5 | 55 | 46 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 10x6 | 10 | 111 | 92 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 15x6 | 15 | 166 | 138 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 20x6 | 20 | 221 | 184 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 30x6 | 30 | 332 | 277 | B=2400 H=2200 T=600 | ≈ 900 |
| MF 5x7 | 5 | 65 | 54 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 10x7 | 10 | 129 | 108 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 15x7 | 15 | 194 | 161 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 20x7 | 20 | 258 | 215 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 30x7 | 30 | 387 | 323 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 5x8 | 5 | 74 | 61 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 10x8 | 10 | 148 | 123 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 15x8 | 15 | 221 | 184 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 20x8 | 20 | 295 | 246 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 30x8 | 30 | 443 | 369 | B=2400 H=2200 T=600 | ≈ 1000 |
| MF 50 | 50 | 92 | 77 | B=1200 H=2200 T=600 | ≈ 500 |
| MF 75 | 75 | 138 | 115 | B=1200 H=2200 T=600 | ≈ 500 |
| MF 100 | 100 | 184 | 154 | B=1200 H=2200 T=600 | ≈ 500 |
| MF 150 | 150 | 277 | 231 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 200 | 200 | 369 | 307 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 250 | 250 | 461 | 384 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 250 (320) | 250 | 590 | 492 | B=1400 H=2200 T=600 | ≈ 600 |

| | | | | | |
|----------------------|---------------|-----|-----|----------------------|--------|
| MF 50-2A | 50 | 92 | 77 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 75-2A | 75 | 138 | 115 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 100-2A | 100 | 184 | 154 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 150-2A | 150 | 277 | 231 | B=1600 H=2200 T=600 | ≈ 800 |
| MF 200-2A | 200 | 369 | 307 | B=1600 H=2200 T=600 | ≈ 800 |
| MF 250-2A | 250 | 461 | 384 | B=1600 H=2200 T=600 | ≈ 800 |
| MF 50x2 | 50 | 184 | 154 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 75x2 | 75 | 277 | 231 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 100x2 | 100 | 369 | 307 | B=1400 H=2200 T=600 | ≈ 600 |
| MF 150x2 | 150 | 553 | 462 | B=1400 H=2200 T=1200 | ≈ 1200 |
| MF 200x2 | 200 | 738 | 616 | B=1400 H=2200 T=1200 | ≈ 1200 |
| MF 250x2 | 250 | 922 | 768 | B=1400 H=2200 T=1200 | ≈ 1200 |
| MF 300 | 300 | 553 | 462 | B=2000 H=2200 T=600 | ≈ 1100 |
| MF 400 | 400 | 738 | 616 | B=2000 H=2200 T=600 | ≈ 1100 |
| MF 500 | 500 | 922 | 768 | B=2000 H=2200 T=600 | ≈ 1100 |
| MF 300-2A | 300 | 553 | 462 | B=2000 H=2200 T=600 | ≈ 1100 |
| MF 400-2A | 400 | 738 | 616 | B=2000 H=2200 T=600 | ≈ 1100 |
| MF 500-2A | 500 | 922 | 768 | B=2000 H=2200 T=600 | ≈ 1100 |
| HF | | | | | |
| HF 25 | 25 | 48 | 40 | B=1200 H=2200 T=600 | ≈ 500 |
| HF 35 | 35 | 67 | 56 | B=1200 H=2200 T=600 | ≈ 500 |
| HF 50 | 50 | 96 | 80 | B=1200 H=2200 T=600 | ≈ 500 |
| HF 75 | 75 | 144 | 120 | B=1200 H=2200 T=600 | ≈ 500 |
| HF 100 | 100 | 192 | 160 | B=1200 H=2200 T=600 | ≈ 500 |
| HF 25-2A | 25 | 48 | 40 | B=1400 H=2200 T=600 | ≈ 600 |
| HF 35-2A | 35 | 67 | 56 | B=1400 H=2200 T=600 | ≈ 600 |
| HF 50-2A | 50 | 96 | 80 | B=1400 H=2200 T=600 | ≈ 600 |
| HF 75-2A | 75 | 144 | 120 | B=1400 H=2200 T=600 | ≈ 600 |
| HF 100-2A | 100 | 192 | 160 | B=1400 H=2200 T=600 | ≈ 600 |
| HF 25x2 | 25 | 192 | 80 | B=1400 H=2200 T=600 | ≈ 600 |
| HF 35x2 | 35 | 96 | 80 | B=1400 H=2200 T=600 | ≈ 600 |
| HF 50x2 | 50 | 135 | 112 | B=1400 H=2200 T=600 | ≈ 600 |
| HF 75x2 | 75 | 192 | 160 | B=1400 H=2200 T=600 | ≈ 600 |
| HF 100x2 | 100 | 385 | 321 | B=1600 H=2200 T=600 | ≈ 600 |
| HF 150 | 150 | 289 | 241 | B=1400 H=2200 T=600 | ≈ 600 |
| HF 200 | 200 | 385 | 321 | B=1600 H=2200 T=600 | ≈ 800 |
| HF 150x2 | 150 | 577 | 482 | B=1400 H=2200 T=1200 | ≈ 1200 |
| LF | | | | | |
| LF 50 | 50 | 92 | 77 | B=1400 H=2200 T=600 | ≈ 600 |
| LF 100 | 100 | 184 | 154 | B=1400 H=2200 T=600 | ≈ 600 |
| LF 150 | 150 | 277 | 231 | B=1400 H=2200 T=600 | ≈ 600 |
| LF 200 | 200 | 369 | 307 | B=1400 H=2200 T=600 | ≈ 600 |
| LF 50x2 | 50 | 184 | 154 | B=1400 H=2200 T=1200 | ≈ 1200 |
| LF 100x2 | 100 | 369 | 307 | B=1400 H=2200 T=1200 | ≈ 1200 |
| LF 150x2 | 150 | 553 | 462 | B=1400 H=2200 T=1200 | ≈ 1200 |
| LF 200x2 | 200 | 738 | 616 | B=1400 H=2200 T=1200 | ≈ 1200 |
| DF | | | | | |
| DF 75/200 | 75/200 | 385 | 321 | B=2000 H=2200 T=600 | ≈ 1100 |
| DF 75/150 | 75/150 | 289 | 241 | B=2000 H=2200 T=600 | ≈ 1100 |
| DF 150/150 | 150/150 | 289 | 241 | B=2000 H=2200 T=600 | ≈ 1100 |
| DF 150/75 | 150/75 | 289 | 241 | B=2000 H=2200 T=600 | ≈ 1100 |
| DF 200/150 | 200/150 | 385 | 307 | B=2000 H=2200 T=600 | ≈ 1100 |
| DF 200/75 | 200/75 | 385 | 307 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF | | | | | |
| SDF 50 (25/25) | 50 (25/25) | 96 | 80 | B=1200 H=2200 T=600 | ≈ 500 |
| SDF 50-2A (25/25) | 50 (25/25) | 96 | 80 | B=1200 H=2200 T=600 | ≈ 500 |
| SDF 110 (75/35) | 110 (75/35) | 212 | 176 | B=1600 H=2200 T=600 | ≈ 1000 |
| SDF 110-2A (75/35) | 110 (75/35) | 212 | 176 | B=1600 H=2200 T=600 | ≈ 1000 |
| SDF 150 (115/35) | 150 (115/35) | 289 | 241 | B=1600 H=2200 T=600 | ≈ 1000 |
| SDF 150 (100/50) | 150 (100/50) | 289 | 241 | B=1600 H=2200 T=600 | ≈ 1000 |
| SDF 150-2A (115/35) | 150 (115/35) | 289 | 241 | B=1600 H=2200 T=600 | ≈ 1000 |
| SDF 150-2A (100/50) | 150 (100/50) | 289 | 241 | B=1600 H=2200 T=600 | ≈ 1000 |
| SDF 185 (75/110) | 185 (75/110) | 356 | 297 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 185 (150/35) | 185 (150/35) | 356 | 297 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 185-2A (75/110) | 185 (75/110) | 356 | 297 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 185-2A (150/35) | 185 (150/35) | 356 | 297 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 225 (75/150) | 225 (75/150) | 434 | 362 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 225 (150/75) | 225 (150/75) | 434 | 362 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 225-2A (75/150) | 225 (75/150) | 434 | 362 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 225-2A (150/75) | 225 (150/75) | 434 | 362 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 235 (200/35) | 235 (200/35) | 452 | 378 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 235-2A (200/35) | 235 (200/35) | 452 | 378 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 260 (75/185) | 260 (75/185) | 500 | 418 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 260 (150/110) | 260 (150/110) | 500 | 418 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 260-2A (75/185) | 260 (75/185) | 500 | 418 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 260-2A (150/110) | 260 (150/110) | 500 | 418 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 275 (200/75) | 275 (200/75) | 530 | 442 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 275-2A (200/75) | 275 (200/75) | 530 | 442 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 300 (75/255) | 300 (75/225) | 577 | 482 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 300 (150/150) | 300 (150/150) | 577 | 482 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 300 (200/100) | 300 (200/100) | 577 | 482 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 300-2A (75/225) | 300 (75/225) | 577 | 482 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 300-2A (150/150) | 300 (150/150) | 577 | 482 | B=2000 H=2200 T=600 | ≈ 1100 |
| SDF 300-2A (200/100) | 300 (200/100) | 577 | 482 | B=2000 H=2200 T=600 | ≈ 1100 |